

Work Order ID 93952

93952

Page 1

December-07-12 2:28:40 PM

Item ID: D350-636-045

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Wearshoe

Start Date: 11/27/12 Start Qty: 1.00

1

Cust Item ID:

Required Date: 11/28/12 Req'd Qty: 1.00

1

Customer: CU-DAR001

Reference: RMA RA111440

RETURN

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
IIN-D350-636	I

100

0.00

100

QC

Quality Control

Memo

INSPECT RA111440

1 X D350-636-045 B91667 CHG001

0.00

DAS 16

12/12/12

110

0.00

110

Packaging

Packaging

Memo

REPACKAGE USING NEW B/N

NEW LABELS AND PAPERWORK REQ'D @ CHG001

0.00

FG 061

HJ for MLT 12-12-10

8 12/12/12 DAS 20

120

QC21- Final Inspection - Work Order Release

0.00

120

QC

Quality Control

Memo

0.00

12/12/11

ME 12-12-71

Picklist Print

December-07-12 2:28:39 PM

Page 1

Work Order ID: 93952

Parent Item: D350-636-045

Parent Item Name: Wearshoe

Start Date: 11/27/12

Required Date: 11/28/12

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:A 08-05-22 new issue DD verified by:ec

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D350-636-045 Wearshoe		Manufactured	No				Each	0.0000		1			

9/6/67

h

RA111440 D350-636-045

B91667

Received @ Dart November 19th, 2012
Inspected@ Dart November 26th, 2012

Customer: AMERICAN EUROCOPTER
Customer Contact: LOIS SMITH
Shipped from: GRAND PRAIRE TX, USA

Instructions for RA 111440 D350-636-045 B91667 CHG001

- Kit is complete
- Needs new paper work and labels
- Needs new BATCH # to go back into stock
- Needs new work order

Time Estimate = 1 HOUR ONLY (stores)

Departments Required: Stores (restocking)

Pictures Attached = NO

QTY INSPECTED = x2

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!!**